


# Notice About Asbestos Materials



**All** Construction and Demolition material coming into the Transfer Station **MUST** be accompanied with an Asbestos Clearance Certification from a Certified Asbestos Inspector or Abatement Company as required by the DEQ and Landfill. This certification is required regardless of the date the material was removed from the property. **No Exceptions.**

We appreciate your cooperation and effort in following these guidelines to keep yourself, our employees and environment safe.



**Southern Oregon Sanitation Inc.**  
P.O. Box 6000 • Grants Pass, OR 97527  
[www.sosanitation.com](http://www.sosanitation.com)

## Asbestos Containing Materials

Acoustical Plaster	Ceiling Tiles and Lay-in Panels	Ductwork Flexible Fabric Connections	Fire Doors	Laboratory Hoods/ Table Tops	Spray-Applied Insulation
Adhesives	Cement Pipes	Electric Wiring Insulation	Fireproofing Materials	Packing Materials (for wall/floor penetrations)	Thermal Taping Compounds
Asphalt Floor Tile	Cement Siding	Electrical Cloth	Flooring Backing	Pipe Insulation (corrugated air-cell, block, etc.)	Textured Paints/ Coatings
Base Flashing	Cement Wallboard	Electrical Panel Partitions	Heating and Electrical Ducts	Roll Roofing	Thermal Paper Products
Blown-in Insulation	Chalkboards	Elevator Brake Shoes	High Temperature Gaskets	Roof Patching Cement	Vinyl Floor Tile
Boiler Insulation	Construction Mastics (floor tile, carpet, ceiling tile, etc)	Elevator Equipment Panels	HVAC Duct Insulation	Roofing Felt	Vinyl Sheet Flooring
Breaching Insulation	Cooling Towers	Fire Blankets	Joint Compounds	Roofing Shingles	Vinyl Wall Coverings
Caulking/Putties	Decorative Plaster	Fire Curtains	Laboratory Gloves	Spackling Compounds	Wallboard

\*\*Accepted materials without a report; bare wood, bare glass, bare metal, and 3-tab roofing and household garbage only\*\*

# Requirements for Construction & Demolition Materials



- It is required that a Licensed Inspector & Abatement contractor come out to the job site. You may not take the samples yourself.
- You must have an Asbestos Clearance Certification, inspection and laboratory report with you for review at our Transfer Station.
- If any suspect material is in your load and has not been tested and cleared, your entire load will be rejected.

## EXCEPTIONS

- Bare wood, metal or glass does not require Asbestos Inspection, Testing or Clearance Certification.
- A laboratory report from a self-taken sample will be accepted IF; you are the **primary resident** and are disposing **one** suspect Asbestos Containing Material only.
- The Oregon DEQ has the discretion to approve requests to waive the asbestos survey requirement on a case-by-case basis.

## Local Licensed Asbestos Inspectors

First Response Environmental Services  
PO Box 3323  
Central Point, OR 97502  
541-621-0911

Western States Environmental Services  
877 Beatty Street  
Medford, OR 97501  
541-770-2482

Coleman Creek Consulting  
PO Box 1926  
Phoenix, OR 97535  
541-535-7108

Asbestos Specialties  
201 Twin Pines Drive  
Glendale, OR 97442  
541-832-2615

\*This does not constitute an endorsement by Southern Oregon Sanitation